



After heavy rainfall during the last week, parts of the Communes Port Salut and Arniquet, and up to Tiburon have become difficult to access. The bridge and passages in Port Salut cannot be crossed by car. An alternative route via Arniquet is also impassable. People can only cross the rivers to get to Port Salut or Arniquet by boat or foot. (Situation 24. April 2017)



The alternative route to Port Salut via Arniquet is also not accessible, due to gullies that formed on the gravelroad.



The alternative passage upstream can be crossed by 4x4, but the bank on the northern side is too steep to climb by car.



The bridge on the main road at Port Salut has been destroyed.



Along the route between Torbeck and Port Salut, debris is blocking parts of the road in several locations.



- Bridge (functional)
- Bridge (destroyed)
- Road or Passage (affected)
- Road or Passage (not accessible)
- Primary Road
- Secondary Road
- River
- Boundary "Commune"
- Boundary "Section Communale"

Data sources:
 REACH: Road Accessibility (24 Apr. 2017)
 CNIGS: Administrative Boundaries
 Openstreetmap: Roads, Places
 Coordinate System:
 File: REACH_Haiti_Sud_Accessibility_20170424
 Contact: reach.mapping@impact-initiatives.org

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.

