


ZIMBABWE - Chimanimani Area

Tropical Cyclone - Impact map

Observed the 20/03/2019

Location Diagrams



Cartographic Information

0 1 2 km
 Local projection: UTM Zone 36S, Datum: WGS 84
 Geographic projection: Lat/Lon (DMS), Datum: WGS 84
 Scale: 1:25 000 for A1 prints

Legend

Crisis information	Roads
Road block	Primary
Bridge - Damaged	Secondary
Industry - Affected	Local road
Flood traces	Hydrology
Landslides	River

Interpretation

Tropical Cyclone Idai passed over eastern Zimbabwe on the 14 March 2019 killing at least 80 people with hundreds more missing. The death toll is expected to rise as authorities continue rescue efforts. This map presents the damage assessment in the Chimanimani area.

Data Sources

Crisis layers
 Flooded and impacts derived from Pléiades-1A image acquired the 20/03/2019
 © SERTIT 2019
 Reference layers
 © OpenSteertMap contributors 2019
 Background layers
 Pléiades-1A © CNES (2019), distributed by Airbus DS, acquired on 20/03/2019 at 07:49 UTC, GSD 0.5 m.
 Spot-7 © Airbus DS (2018), acquired on 24/06/2018 at 07:41 UTC, GSD 1.5 m.

Framework

The products elaborated for this Rapid Mapping Activity are realised to the best of our ability, within a very short time frame, during a crisis/exercice, optimising the material available.
 All geographic information has limitations due to the scale, resolution, date and interpretation of the original source materials. No liability concerning the content or the use thereof is assumed by the producer.

Map produced the 20 03 2019 by SERTIT
 © SERTIT 2019

sertit@sertit.u-strasbg.fr
<http://sertit.u-strasbg.fr>



© SERTIT 2019